



NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000

September 23, 2014

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
Room W48-302
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Ms. Lewis:

This letter amends our August 11, 2014 letter concerning the regional field action Nissan began undertaking on certain Nissan and Infiniti vehicles equipped with specific Takata passenger air bag inflators manufactured between January 1, 2003 and July 31, 2004.

We are pleased to inform you that Nissan has identified the potentially affected Nissan Sentra and Infiniti M35/45 vehicles. We have completed the vehicle identification process and the updated list of potentially affected vehicles immediately below.

Model	Number of Vehicles
MY 2003-2004 Nissan Pathfinder	3,563
MY 2004-2006 Nissan Sentra	18,097
MY 2003-2005 Infiniti FX35/FX45	6,203
MY 2003-2004 Infiniti I35	1,780
MY 2006 Infiniti M35/M45	355

Very truly,

Donald Neff
Manager, Technical Compliance