



SAFETY RECALL NOTICE: 14V-452

TO: All Dealers

Collins Bus Corporation has decided that a safety defect exists in certain Collins, Mid Bus, and Corbeil buses. Accordingly, a recall to address this issue is being initiated effective immediately.

During an audit of a vehicle in the production process, inspectors observed incorrect clamp location of the liquid propane line resulting in the potential contact between the third body mount bolt on the left rear of the frame rail and a propane fuel line. Movement of the body and chassis may cause interference between the liquid propane line and the body mount bolt, and this interference could damage the propane fuel line and cause a failure to the propane fuel system.

Owners will be notified by mail about the recall and will be instructed to contact you for inspection and repair. If the defect exists, detailed instructions and drawings will be provided for the relocation of the liquid propane fuel line. The estimated inspection and repair time is 15 minutes per vehicle. There is no cost to owners for this recall.

The attached list identifies buses shipped to you which have not yet been registered to end-users. If you are in possession of any of these buses, please perform the necessary repairs as soon as possible. If a customer has taken delivery of a vehicle included in this Safety Recall, please contact the customer and schedule repairs.

Please be reminded that it is a violation of Federal law for you to sell or lease the buses covered by this notification until this recall has been performed on these buses. Substantial civil penalties apply to violations of this law.

Your assistance with this recall is appreciated. Should you have any questions or concerns, please contact:

Ginger Markus, Warranty Coordinator
Collins Bus Corporation
415 West 6th Street
South Hutchinson, KS 67505
(800) 533-1850, ext. 424
Email: ginger.markus@collinsbus.com
Fax: (620) 662-3838

Sincerely,
Collins Bus Corporation