



11/26/2014

New Safety Recall Advanced Communication – P40112614

Chrysler Group LLC (Chrysler) announced a safety recall on certain vehicles originally sold or currently registered in Florida, Hawaii, Puerto Rico and the U.S. Virgin Islands:

- 2003 – 2007 MY (DR) Dodge Ram 1500/2500/3500 Pickup
- 2005 – 2007 MY (DH) Dodge Ram 2500 Pickup
- 2006 – 2007 MY (D1) Dodge Ram 3500 Pickup
- 2007 MY (DC) Dodge Ram 3500 Cab Chassis
- 2004 – 2007 (HB) Dodge Durango
- 2007 MY (HG) Chrysler Aspen
- 2005 – 2007 MY (LX) Chrysler 300, Dodge Magnum and Dodge Charger
- 2005 – 2007 (ND) Dodge Dakota

The driver and/or passenger airbag inflator housing in your vehicle may rupture, due to excessive internal pressure, during normal airbag deployment events. This condition is more likely to occur if your vehicle has been exposed to high levels of absolute humidity for extended periods of time. Excessive internal pressure, during airbag deployment events, could result in an increased chance of occupant injury during certain crash conditions.

Chrysler will conduct a voluntary safety recall on all involved vehicles to replace the driver and/or passenger airbag inflator.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
Chrysler Group LLC