

Recall Quarterly Report**14V-344**

Manufacturer Name : Mazda North American Operations
NHTSA Recall No. / MFR Recall No. : 14V-344 /7914J
Recall Subject : Driver Side Frontal Air Bag Inflator may Rupture
Owner Notification Date : OCT 17, 2014 -



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 29, 2015	2014-4	330,000	5,394	3,110	138

This Document Last Updated : FEB 04, 2015

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.