



Ford Motor Company
 Ford Customer Service Division
 P. O. Box 1904
 Dearborn, Michigan 48121



59/000030/0001



R. FILE
 330 TOWN CENTER DR
 STE 500
 DEARBORN, MI 48126-2796

January 2015

***** IMPORTANT SAFETY RECALL *****
(PROGRAMA DE SEGURIDAD IMPORTANTE)

Safety Recall Notice 14B04 / NHTSA Recall 14V-343
Aviso de Revisión de Seguridad 14B04

This notice applies to your vehicle:

2005 Ranger

Your Vehicle Identification Number:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the Vehicle Identification Number shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? In certain vehicles, continued exposure to areas with high levels of absolute humidity may cause the front driver side air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the driver side frontal airbag. An inflator rupture could result in metal fragments striking and potentially seriously injuring vehicle occupants. Coverage is automatically transferred to subsequent owners.

What will Ford and your dealer do? Ford Motor Company has authorized your dealer to replace the driver airbag inflator free of charge (parts and labor).

How long will it take? The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do? Please call your dealer without delay and request a service date for Safety Recall 14B04. Provide the dealer with the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed near your name at the beginning of this letter.

If you do not already have a servicing dealer, you can access www.Fordowner.com for dealer addresses, maps, and driving instructions.

Ford Motor Company wants you to have this service action completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What if you no longer own this vehicle?

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

Can we assist you further?

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

RETAIL OWNERS: If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332** and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

For the hearing impaired call 1-800-232-5952 (TDD). Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.

FLEET OWNERS: If you have questions or concerns, please contact our **Fleet Customer Information Center at 1-800-34-FLEET**, choose Option #3, and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: www.fleet.ford.com.

Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to www.safercar.gov. Reference NHTSA Safety Recall 14V-343.

Thank you for your attention to this important matter.

Ford Customer Service Division