



Harley-Davidson Motor Company, 3700 West Juneau Ave., PO Box 653, Milwaukee, WI 53201 414/342-4680

\*\*\*\*\*AUTO\*\*3-DIGIT 530 P1 C1 ##



## IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN # 1HD4 

April 27, 2015

Harley-Davidson Recall No. 0620

NHTSA Recall No. 15V-217

Dear Harley-Davidson Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that certain model year 2015 Street family motorcycles fail to conform to Federal Motor Vehicle Safety Standard No. 108, Lamps, reflective devices, and associated equipment. These motorcycles may have been built without a rear reflector, P/N 59988-72A. We are notifying you because our records indicate that you have purchased one of the affected motorcycles.

### What is the Issue?

Federal Motor Vehicle Safety Standard No. 108 requires that new motorcycles be equipped with a red reflex reflector on the rear of the motorcycle. Due to a production error, this reflector may have been omitted from your motorcycle. The absence of this reflector could reduce the rear conspicuity of the vehicle, possibly increasing the risk of a crash.

### What Should You Do?

Please contact your authorized Harley-Davidson motorcycle dealer immediately and arrange an appointment to have your motorcycle repaired. Your dealer will confirm that your motorcycle is covered by this recall. If covered, the dealer will install the rear reflector bracket subassembly from the recall kit provided by Harley-Davidson at no cost to you. The repair will take less than one half hour to perform. However, due to scheduling, the dealer may require your motorcycle

for a longer period of time. To verify that the service has been completed, your dealer will ask you to sign a recall claim.

If you have sold your motorcycle and have an address for the current owner, it is important that you forward this notice to the new owner. Alternatively, you may contact us at the Harley-Davidson phone numbers listed below and provide us the contact information for your purchaser so that we may notify the new owner of this recall. Also, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

### **What If You Have Additional Questions or Concerns?**

If you take your motorcycle to your dealer on a mutually agreed upon date and they are unable to perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at 1-800-258-2464 in the U.S. or 1-414-343-4056 world-wide.

If you are still having difficulty getting your vehicle repaired in a reasonable time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.  
Recall 0620