



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 26, 2015

Mr. Barry Stiles
President
Fleetline
784 Bill Jones Industrial Dr
Springfield, TN 37172

NVS-215MR
15E-038

Subject: Fender Brackets may Separate

Dear Mr. Stiles:

This letter serves to acknowledge Fleetline's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FLEETLINE/FENDER BRACKET/9999
NU-LINE/FENDER BRACKET/9999

Mfr's Report Date: May 7, 2015

NHTSA Campaign Number: 15E-038

Components:
EQUIPMENT

Potential Number of Units Affected: 3,200

Problem Description:

Fleetline is recalling certain Nu-Line and Fleetline Fender Brackets and Fender Kits with Fender Brackets, part numbers N230PMLH, N230PMRH, N230-19L, N230-19R, 1650-1, 1650-2, 1650-7 and 1650-8, manufactured January 1, 2015, to April 13, 2015. Due to an insufficient weld, portions of the affected fender brackets may separate, causing the fender to not be properly supported.

Consequence:

If the fender is not supported, it may contact the tires, and the fender may be torn from the vehicle, creating a road hazard and increasing the risk of a crash.

Remedy:

Fleetline will notify the end users who will be offered replacement brackets that bolt on, free of charge. The recall is expected to begin in May 2015. Owners may contact Fleetline customer service at 1-615-382-6100.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Fleetline's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement