

IMPORTANT SAFETY NOTICE

This notice applies to your vehicle, see the attached Engine Serial Number/VIN list

June 2, 2015

Gillig Campaign ID Number: 15V-262

«AddressBlock»

Attn: «FirstName»

This notice is sent to you in accordance with National Traffic and Motor Vehicle Safety Act.

Gillig has decided, based on information supplied by Cummins, that a defect which relates to motor vehicle safety exists in ISLG-equipped buses built between 8/26/2010 and 4/30/2015. VIN's, as identified by the Engine Serial Numbers provided by Cummins is attached.

What The Issue Is:

Under conditions of excessive crankcase pressure, the 90 degree elbow of the vent tube assembly may become detached from the breather, possibly allowing engine oil to come in contact with hot surfaces. Engine oil contacting hot surfaces may ignite, possibly resulting in a fire.

**What We Are Asking
You To Do:**

- 1. Contact your local Cummins Dealer to schedule having clamps added to this vent assembly and a new calibration uploaded in the ECM to lower the crankcase pressure, should the pressure exceed normal limits. The repair will be completed free of charge and most applications will require approximately 1 hour to complete.*
- 2. Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.*
- 3. If you have already performed this repair, you may be eligible to receive reimbursement for the cost of performing the repair which is the subject of this recall. For more information contact Gillig Service at 800.735.1500, or your local Cummins Deal*

Gillig Campaign ID Number: 15V-262

<Date>

Page 2

**What Gillig Will Do
For You:**

1. We will assist in getting you in contact with your local Cummins Dealer, if needed.

If You Have Concerns:

Any questions regarding the information should be directed to Gillig Field Service, (800.735.1500) available from 6 AM until 3:30 PM, Monday through Friday, or your local Cummins Dealer

If there is a failure to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience that this situation may cause you. Gillig wants to assure you that we are concerned about customer safety and your continued satisfaction with our products.

Sincerely,

THE GILLIG CORPORATION



Robert L. Birdwell
Executive Director, Quality & Service

RLB:rlb
Encl.

CC: Mr. Greg Vismara, V.P., Engineering, Gillig

CumminsISLGVent&CALRecall.nhtsa

C:\My Documents\Bob\Bird\Documents\2012\Ricon\HandleRecall.nhtsa.wpd