

DAIMLER

Defect Information Report (Section 573.6)

FL-683

Date of Submission: 6/9/2015

Manufacturer: Daimler Trucks North America LLC
P.O. BOX 3849
Portland, Oregon 97208

Type of Report: Safety Defect Non-Compliance

Vehicle Information

Model Yr. Start: 2015 Model Yr. End: 2015
Make: Western Star
Model: 4700, 4800, 4900
Production Dates: Begin: 11/15/14
End: 01/30/15

Descriptive Information:

Western Star vehicles using suspected speedometer.

Number potentially involved: 21 Estimated percentage of involve with defect: 100%

Defect / Noncompliance Description

Describe the defect or noncompliance:

The speedometer on certain Western Star vehicles may not operate as intended. In certain circumstances, the speedometer may not display the vehicle speed.

If a noncompliance, provide the applicable FMVSS:

FMVSS 393.82.

Describe the safety risk:

None, non-compliance report only.

If applicable, identify the manufacture of the defective or noncompliant component.

PACIFIC INSIGHT ELECTRONICS CORPS

DAIMLER

Chronology of Defect / Noncompliance Determination

Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision.

April 2015-DTNA received notification and began investigating a potential issue with the speedometer not functioning correctly on certain Western Star vehicles.

June 2015 - DTNA decided to initiate a voluntary recall campaign.

Identify the Remedy

Describe the defect/noncompliance remedy program, including the manufacture's plan for reimbursement.

The affected vehicles will have a new speedometer installed. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

Identify the Recall Schedule


Describe the recall schedule for notifications.:

Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Begin Date:	08/07/2015
Planned Dealer Notification End Date:	08/07/2015
Planned Owner Notification Begin Date:	08/07/2015
Planned Owner Notification End Date:	08/07/2015

Manufacture's identification code for this recall (if applicable): FL-683

DTNA Representative;



Andy Jones
Senior Manager
Compliance and Regulatory Affairs