

GM CUSTOMER CARE AND AFTERSALES  
DCS3750  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 17, 2015

Subject: 15504A – Noncompliance Recall  
Radio Lockup with Loss of Chimes  
Customer Letter Added

Models: 2014-2015 Chevrolet Spark Equipped with RPO UM7 & UE1  
2015 Chevrolet Sonic Equipped with RPO UH7/UM7 & UE1  
2015 Chevrolet TRAX (Canada) Equipped with RPO UMT & UE1

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New and Used Vehicle Sales  
Manager, and Warranty Administrator

Bulletin 15504 has been revised to include a copy of the customer letter. Please discard all copies of bulletin 15504.

**Customer Letter Mailing**

The customer letter mailing began on August 11, 2015.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES