



VT Hackney

A company of VT Systems

VT Hackney, Inc.

911 W. Fifth Street P.O. Box 880

Washington, North Carolina 27889, USA

Phone: 252.946.6521

Fax: 252.975.8340

www.vthackney.com

IMPORTANT SAFETY RECALL

This notice applies to your vehicle "vin" attached

SAFETY RECALL # 15V-437

JULY 2015

Dear Kidron Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kidron has decided that certain model year 2014-2015 Refrigerated trailers there is a defect in the main harness that supplies power to the 7 pin connector for doubles operation.

Reason for this recall:

There is a defect in the main harness that supplies power to the 7 pin connector for doubles operation on trailers 35' long and longer. The ABS of the second trailer may not have adequate power from the primary circuit.

Risk to motor vehicle safety:

The ABS of the second trailer may not have adequate power from the primary circuit. This could result in increased braking distances in an emergency brake application possibly resulting in a vehicle crash.

Actions you should take:

Immediately contact Gene Newman of VT-Hackney to receive corrective action instructions at 252-975-8399. The corrective action is estimated to take 1.5 hours to complete

A second harness to provide power to the rear 7 pin connector must be added. The required harness will be available as of July 30, 2015 at no cost to you.

If you do not own this vehicle:

Our records indicate you are the owner of the vehicle identified on the enclosed card. If you do not own this vehicle, please fill out the **Authorization for Recall Service card** so you will not be contacted again regarding this recall.

If you need assistance:

If you believe that Kidron has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please contact VT Hackney 800-763-0700.

You may also wish to submit a complaint to:

Administrator

National Highway Traffic Safety Administration,

1200 New Jersey Ave. S.E.

Washington, D.C., 20590

Or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152) or go to www.safercar.gov

Lessor Requirements:

Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice to the lessee within ten days.

Reimbursement Eligibility:

If you have previously paid for repairs as a result of this defect, you may be entitled to recovery of those expenses. Contact Kidron for details.

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

Sincerely,

Gene Newman
Manager, Warranty
Kidron division of VT Hackney, Inc.