



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 22, 2015

Ms. Patricia Dolson
General Counsel & Corporate Secretary
Holley Performance Products, Inc
1801 Russellville Rd
Bowling Green, KY 42101

NVS-215KS
15E-070

Subject: Solenoid End-Stop Sleeves May Break

Dear Ms. Dolson:

This letter serves to acknowledge Holley Performance Products, Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NOS/NITROUS OXIDE SYSTEM/9999

Mfr's Report Date: August 25, 2015

NHTSA Campaign Number: 15E-070

Components:

FUEL SYSTEM, OTHER:FUEL INJECTION SYSTEM

Potential Number of Units Affected: 1,020

Problem Description:

Holley Performance Products, Inc. (Holley) is recalling certain NOS-brand Nitrous Oxide systems manufactured May 1, 2015, to August 17, 2015. The affected nitrous oxide systems have solenoid valves that may fracture when the fuel system is pressurized.

Consequence:

If the valve fractures, portions of the valve may become projectiles, increasing the risk of injury to those nearby or possibly damaging other nearby components.

Remedy:

Holley will notify owners and will repair or replace the solenoid valves, free of charge. The recall is expected to begin in September 2015. Owners may contact Holley customer service at 1-800-638-0032.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Holley's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement