



---

09/24/2015

## **New Safety Recall Advanced Communication – R52092415**

FCA US LLC announced a safety recall on certain 2016 model year (DJ / D2 / DD / DP) RAM trucks equipped with a 6.7L Cummins diesel engine.

The Engine Control Module (ECM) on some of the above vehicles may have been damaged during the manufacturing process. One of the ECM printed circuit board retaining screws may have damaged the edge of the printed circuit board. This can cause a short circuit to ground condition within the ECM. Should the printed circuit board short to ground, there could be a loss of motive power. A loss of motive power, during certain driving conditions, could cause a crash without warning.

FCA will conduct a voluntary safety recall on all involved vehicles. The ECM on all involved vehicles must be replaced.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations  
FCA US LLC