



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 7, 2015

Ms. Lisa Hancock
Corporate Recall Administrator
Blue Bird Body Company
402 Blue Bird Blvd
Fort Valley, GA 31069

NVS-215KS
15V-591

Subject: Engine Control Module may Short Circuit

Dear Ms. Hancock:

This letter serves to acknowledge Blue Bird Body Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BLUE BIRD/VISION/2016

Mfr's Report Date: September 21, 2015

NHTSA Campaign Number: 15V-591

Components:

ELECTRICAL SYSTEM:IGNITION:MODULE
ENGINE AND ENGINE COOLING:ENGINE

Potential Number of Units Affected: 2

Problem Description:

Blue Bird Body Company (Blue Bird) is recalling certain model year 2016 Vision school buses manufactured on August 16, 2015. In the affected vehicles, the Engine Control Module (ECM) may short circuit, causing the engine to stall without warning.

Consequence:

An engine that stalls without warning increases the risk of a crash.

Remedy:

Blue Bird will notify owners, and Cummins dealers will replace the ECM, free of charge. The recall is expected to begin October 22, 2015. Owners may contact Blue Bird's customer service number at 1-478-822-2242. Blue Bird's recall number is R15YG-SB.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with the first name being the most prominent.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement