

GM CUSTOMER CARE AND AFTERSALES
DCS3872
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 10, 2015

Subject: 15299B – Safety Recall
Driver Side Rear Pillar Interior Fires
Revised Owner Manual Insert and Correction

Models: 2013-2016 Cadillac ATS Sedan

To: All Cadillac Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales Manager,
Service Manager, Parts and Service Director, New Vehicle Sales
Manager, Used Vehicle Sales Manager

Bulletin 15299A has been updated to update the Correction paragraph and the Owner Manual Insert. Please discard all copies of 15299A.

Customer Letter Mailing

The customer letter mailing began on October 16, 2015.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES