

## Federal Recall Information

15KWM

### Supplier

Cummins Inc.

### Description

Cummins ISB6.7, ISL9, ISX12, ISX15, QSX15 T4 CM2350 ECM Safety Campaign

### Release Date

10/19/2015

### Introduction

Cummins ISB6.7, ISL9, ISX12, ISX15, QSX15 T4 CM2350 ECM Safety Campaign

### Situation

Cummins has discovered that during installation of Printed Circuit Boards (PCB's) into the ECM case at the supplier, a screw became misaligned resulting in damage to the PCB's creating a short circuit. This could blow a fuse in the ECM's electrical supply circuit, resulting in an engine stall without warning and without the ability to restart. An unexpected engine stall without the ability to restart the engine will increase the risk of a crash.

### Resolution

Cummins will replace the existing, affected ECM with a new ECM.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

### Warranty

File warranty claims through the normal Cummins warranty system.

DWVC and SIR will indicate chassis involved in this recall with the designator of "C1698" in the campaign field.

### Attachments

 [Chassis List](#)

 [Cummins Recall C1698](#) (NOTE: A Cummins QuickServe® login is required)

Authored by: JS

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2015 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).