



**To:** U.S. and Canada Distributors  
Dealer Principals  
Service Managers  
Warranty Managers  
Parts Managers

**Bulletin:** SRA-V16-04  
**Date:** June 9, 2016  
**Action Required?** **YES**

**From:** Regulatory Affairs Department

**Subject:** Safety Recall, RVXX1604, Cummins ISX Engine Control Module

---

**Summary:**

The Engine Control Module may develop an internal electrical short circuit, possibly resulting in an engine stall without warning (and without the ability to restart). This can lead to an increased risk of a crash.

Cummins has released field Campaign C1792 "ISX12 and ISX15 CM2350 ECM Safety Campaign" to correct this condition by replacing the Engine Control Module. This campaign is available at Cummins Distributors and Cummins-authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 2 hours to complete. Contact the nearest Cummins Distributor or Cummins-authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair.

**Models/ Model Years Affected:**

Volvo: Certain 2017 VNL model vehicles manufactured from March 7, 2016 and April 12, 2016 with a Cummins ISX12 and ISX15 Engine.

**Vehicle Quantities:**

Volvo: 131 in total (129 U.S. and 2 Canada).

**Dealer's Responsibility:**

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

**Release Schedule:**

- Vehicle will be posted on the Trucks Dealer Portal June 9, 2016.
- Cummins will administer the recall program.

**Questions:**

If you have questions or concerns about this recall, please contact your local Cummins Distributor. You may also contact the Cummins Customer Assistance Center at 1-800-DIESELS (1-800-343-7357).