



IMPORTANT SAFETY RECALL

January, 2016

**Please contact your Ford dealer today
regarding Recall 15S29**

There is no charge to vehicle owners for recall repairs performed by an authorized dealer. If your dealer has recently completed this recall repair, please disregard this reminder.

Thank you for your attention to this very important matter.

Year/Model: 2015 F-150 Ford Truck

VIN#:

Subject: Adaptive Cruise Control Module Reprogramming

Ford Customer Service Division



P.O. BOX 1904
DEARBORN, MI 48121-1904

PRESORTED
FIRST CLASS
U.S. POSTAGE
PAID
Southgate, MI
Permit No. 227



C / 0001 / 000000000000039



**RECALL
REMINDER**