



March 26, 2014

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE – Room W45-306
Washington, DC 20590

Dear Ms. Lewis:

The following information is submitted pursuant to the requirements of 49 CFR 573.6 as it applies to a determination by General Motors of a noncompliance recall involving 2014 model year Cadillac ELR vehicles.

573.6(c)(1): Cadillac Brand of General Motors Company

573.6(c)(2)(3)(4): This information is shown on the attached sheet.

573.6(c)(5): General Motors has decided that some 2014 model year Cadillac ELR vehicles fail to conform to Federal Motor Vehicle Safety Standard 126, Electronic Stability Control Systems. Vehicles without Adaptive Cruise Control were built with a calibration that inhibits some Electronic Stability Control (ESC) diagnostics. If the subject diagnostics are inhibited, there are some fault conditions that will not be detected if they occur. The ESC malfunction indicator light will not illuminate as required by S5.3 of FMVSS 126, even though ESC functionality will be disabled or degraded. Failure to illuminate the ESC malfunction indicator light when an ESC fault condition is present could result in an increased risk of crashes and injuries.

573.6(c)(7): The Issue was presented to the Field Performance Evaluation Review Committee and on March 19, 2014, the Executive Field Action Decision Committee decided to conduct a noncompliance recall. General Motors will identify the date of each observation that indicated that a noncompliance might or did exist within two weeks.

A stop delivery order was sent to the dealers on March 19, 2014.

573.6(c)(8): Dealers are to recalibrate the Electronic Brake Control Module (EBCM).

GM is sending the dealer bulletin on March 26, 2014 and anticipates mailing the owner letters on or about April 17, 2014.

Pursuant to 577.11(e), GM does not plan to provide notice about reimbursement to owners because all involved vehicles are covered under the new vehicle warranty.



573.6(c)(10): GM will provide the dealer bulletin and owner letter under separate cover.

573.6(c)(11): GM's assigned recall number is 14087.

Sincerely,

A handwritten signature in black ink, appearing to read "M. Carmen Benavides". The signature is fluid and cursive, with the first name "M." and the last name "Benavides" clearly distinguishable.

M. Carmen Benavides, Director
Product Investigations and Safety Regulations

573.6(c)(2)(3)(4)

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR
PLUS INCLUSIVE DATES OF MANUFACTURE

<u>MAKE</u>	<u>MODEL SERIES</u>	<u>MODEL YEAR</u>	<u>NUMBER INVOLVED</u>	<u>INCLUSIVE MANUFACTURING DATES (FROM) (TO)</u>		<u>DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.</u>	<u>EST. NO. W/CONDITION</u>
Cadillac	R	2014	656	09/26/2013	02/14/2014	ELR	*
	GM Total:		656				

* All involved vehicles will be corrected as necessary.

573.6(c)(2)(iv): TRW Automotive
12075 Tech Drive
Livonia Mi, 48150

Seth Bunin
734-855-3004

The EBCM is manufactured in the United States.

14087