



RECEIVED

By Recall Management Division at 6:18 am, May 19, 2014

May 16, 2014

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE – Room W45-306
Washington, DC 20590

Dear Ms. Lewis:

The following information is submitted pursuant to the requirements of 49 CFR 573.6 as it applies to a determination by General Motors to conduct a safety related recall involving 2004 - 2008 model year Chevrolet Aveo vehicles.

573.6(c)(1): General Motors Company, Chevrolet Brand

573.6(c)(2)(3)(4): This information is shown on the attached sheet.

573.6(c)(5): General Motors has decided that a defect which relates to motor vehicle safety exists in 2004 - 2008 model year Chevrolet Aveo vehicles. Heat generated in the vicinity of the daytime running lamp (DRL) module, in the center console in the instrument panel, could melt the DRL module and cause a fire.

573.6(c)(6): On May 16, 2014, the GM North American Executive Field Action Decision Committee decided to conduct a safety recall. General Motors will be submitting a supplemental chronology within two weeks.

573.6(c)(8): General Motors will provide its plan for remedying the defect and its schedule for notifying dealers and owners as soon as they are confirmed.

Pursuant to 577.11, General Motors will provide reimbursement to owners for repairs completed on or before ten days after the owner mailing is completed, according to the plan submitted on May 23, 2013.

573.6(c)(10): General Motors will provide the dealer bulletin and owner letter under separate cover.



Letter to Ms. Nancy Lewis
A140236 573 Letter
May 16, 2014
Page 2

573.6(c)(11): General Motors' assigned recall number is 14236.

Sincerely,

A handwritten signature in black ink, appearing to read "B. Latouf". The signature is fluid and cursive, with the first letter of each name being significantly larger and more stylized.

Brian Latouf, Director
Field Product Investigations & Evaluations

Attachment

573.6(c)(2)(3)(4)

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR
PLUS INCLUSIVE DATES OF MANUFACTURE

<u>MAKE</u>	<u>MODEL SERIES</u>	<u>MODEL YEAR</u>	<u>NUMBER INVOLVED</u>	<u>INCLUSIVE MANUFACTURING DATES (FROM) _____ (TO)</u>	<u>DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.</u>	<u>EST. NO. W/CONDITION</u>
-------------	---------------------	-------------------	------------------------	--	--	-----------------------------

General Motors will provide this information when available.

* All involved vehicles will be corrected as necessary.

573.6(c)(2)(iv):

The supplier of the DRL module is:
Hamsar Diversco Inc.
5320 Downey St.
Burlington, Ontario Canada L7L 6M2

Canada is the country of origin for the DRL module.

14236