

# **MAXZONE AUTO PARTS CORP.**

## **CORPORATE HEADQUARTERS**

15889 SLOVER AVE, UNIT A , FONTANA, CA 92337 TEL: 909-822-3288 FAX: 909-822-3399 WWW.MAXZONE.COM

## **Safety Recall Notice**

**NHTSA Recall Campaign Number: 13E-051**

Date: 2/14/2014

To: Valued Body Shop,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maxzone Auto Parts Corp. has decided that certain DEPO replacement headlamps fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 108 during humidity test. This non-conformance could result in reduced visibility for the driver, increasing the risk of a crash. Please see the details as follow.

	<b>DEPO No.</b>	<b>OEM No.</b>	<b>Partslink No.</b>	<b>Description</b>
1	K30-1122R-AC	5L3Z13008 AB	FO2503201C	FD F-150 04-08 HL ASY RH CAPA
2	K30-1122L-AC2	7L3Z 13008 HA	FO2502247C	FD F-150 06-08 HL ASY W/O CHROME, W/O SHADOW GRAY TRIM LH CAPA
3	K30-1122R-AC2	7L3Z 13008 EA	FO2503247C	FD F-150 06-08 HL ASY W/O CHROME, W/O SHADOW GRAY TRIM RH CAPA
4	K30-1122L-AC6	7L3Z 13008 DA	FO2502248C	FD F-150 07-08 HL ASY W/O CHROME, W/SHADOW GRAY TRIM LH CAPA
5	K30-1122R-AC6	7L3Z 13008 CA	FO2503248C	FD F-150 07-08 HL ASY W/O CHROME, W/SHADOW GRAY TRIM RH CAPA

As an immediate remedy, Maxzone is issuing a recall of the aforementioned product at no cost to you.

Please advise the collision repairers that the products with lot numbers: 20120102 and 20121015 for K30-1122R-AC, 20110905 for K30-1122L/R-AC2 and 20110711 for K30-1122L/R-AC6 are eligible to be recalled. Lot numbers can be found on the product box label, the product label and also stamped on the bottom of the housing. Please see following page for pictures illustrating the lot number locations. Please contact the distributor from which the product was purchased immediately to arrange the return of identified part numbers.

You can identify a DEPO lamp by looking for the DEPO logo and part number molded on the lens in the front side of the lamps. The part numbers shown on the lens are 330-1122L for left hand side lamps and 330-1122R for right hand side lamps. Only lamps with the aforementioned DEPO logo and part numbers can be returned to Maxzone. The recalled lamps will be replaced with corrected DEPO lamps from your distributor. Please see following page for a picture illustrating the logo and part numbers.

If you believe Maxzone has failed or is unable to remedy the noncompliance without charge in a reasonable amount of time, you can submit a complaint to the National Highway Traffic Safety




Administration, 1200 New Jersey Avenue SE, Washington, DC 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-91530) or go to <http://www.safercar.gov>.

We sincerely apologize for any inconvenience caused. Our best interest has always been in the safety of the public. We'll do our best to resolve this issue immediately.

Best regards,


Maxzone Auto Parts Corp.



DEPO part number and lot number on the box label.



DEPO label with part number and lot number on the product label on the bottom of the housing.



Lot number stamped on the bottom of the housing



DEPO logo and part number on lens.

Note: 330-1122L (left hand side lamp) shown above. The part number for right hand side lamp on the lens is 330-1122R.