3328

VEHICLE OWNER'S QUESTIONNAIRE

FOR AGENCY USE ONLY

DATE RECEIVED

cd.dr
st.dt
od.rt
up.tr

REFERENCE NO.

607289

QC'd

Posted

OWNER INFORMATION (TYPE OR PRINT)

NAME & ADDRESS

[redacted]

DAY TIME TELEPHONE NO. (AREA CODE)

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES ☐ NO ☐
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

SIGNATURE OF OWNER

DATE

VEHICLE INFORMATION

VEHICLE IDENTIFICATION NO.	VEHICLE MAKE	VEHICLE MODEL	MODEL YEAR
WBACD432XWAV58900	BMW	328 I	1998

(LOCATED AT BOTTOM OF WINDSHIELD ON DRIVER'S SIDE)

CURRENT ODOMETER READING

DATE PURCHASED 3/98

☒ NEW ☐ USED

DEALER'S NAME, CITY, & STATE: York BMW Valencia, Calif

ENGINE SIZE (CID/CC/L) ____ ☐ TURBO ☐ DIESEL ☐ GAS ☐ FUEL INJECTION

NO. CYLINDERS ____

TRANSMISSION TYPE: ☒ MANUAL ☐ AUTOMATIC

ANTILOCK BRAKES: ☐ YES ☐ NO

RESTRAINT SYSTEM: ☒ DRIVER SIDE AIRBAG ☐ MOTOR BELT ☐ PASSENGER SIDE AIRBAG ☐ 3-POINT BELT ☐ 2-POINT BELT

CRUISE CONTROL: ☒ YES ☐ NO

DRIVETRAIN: ☐ FRONT ☐ REAR ☐ 4-WHEEL

BODY STYLE: ☐ STAWAG ☐ 2 DOOR ☒ 4 DOOR ☐ HATCH BK ☐ VAN ☐ PK UP TRK ☐ OTHER

FAILED COMPONENT(S)/PART(S) INFORMATION

COMPONENT

PART NAME(S): gas meter sensor read empty

LOCATION: ☒ LEFT ☒ RIGHT ☐ FRONT ☐ REAR

FAILED PART(S): ☒ ORIGINAL ☐ REPLACEMENT

NO. OF FAILURES: 1

DATE(S) OF FAILURE(S): 8/98

MILEAGE AT FAILURE(S): 9000

VEHICLE SPEED AT FAILURE(S) ____

MANUFACTURER CONTACTED: ☒ YES ☐ NO

NHTSA PREVIOUSLY CONTACTED: ☐ YES ☐ NO

APPLICABLE ACCIDENT INFORMATION

ACCIDENT	FIRE	NUMBER OF PERSONS INJURED	NUMBER OF FATALITIES	PROPERTY DAMAGE EST $	POLICE REPORT FILED
☐ Yes ☒ No	☐ Yes ☒ No	2	2	____	☐ YES ☐ NO

FAILED TIRE INFORMATION ONLY

TIRE IDENTIFICATION NO.* D O T

MANUFACTURER TIRE NAME

SIZE

* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.

NARRATIVE DESCRIPTION OF FAILURE(S), ACCIDENT(S), INJURY(IES) ON THE BACK

The Privacy Act of 1974
Public Law 93-579

This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

EW-2001-1
(5/19/