

**RE: BODY SERIAL
CHASSIS SERIAL**

Dear Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Our records indicate that you have purchased a vehicle with the serial number which appears above.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2002, 2003, and 2004 model years Winnebago Brave® and Itasca Sunrise®; 2005 and 2006 model years Winnebago Voyage® and Adventurer® and Itasca Sunrise® and Suncruiser®. These motor homes were manufactured November 5, 2001 through April 27, 2006. The propane tank mounting bracket may have an incomplete or improper weld. Should the weld fail, the propane tank can tip or fall, possibly releasing propane which has the potential to ignite, resulting in personal injury and/or vehicle and property damage.

WHAT WE WILL DO

Winnebago Industries, Inc. dealers will inspect and properly weld the bracket if required at no charge to you.

WHAT YOU SHOULD DO

Please contact your Winnebago Industries, Inc. dealer immediately to arrange for an appointment. The labor time necessary to perform this inspection will be approximately one-half hour. Should repair be required, additional time will be necessary. Please allow additional time for the dealer to process your vehicle.

Winnebago Industries, Inc. dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to the dealer on the agreed date and he does not service this condition on that date or within five days, we recommend you contact Winnebago Industries, Inc., Attn.: Owner Relations Representative (641/585-6939). If you are still unable to obtain such service without charge to you and within a reasonable time, you may contact The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 888/327-4236; (TTY: 800/424-9153); or go to <http://www.safercar.gov>.

IF YOU HAVE PREVIOUSLY PAID FOR THIS REPAIR

If you have paid to remedy this issue, you may be eligible for a refund. To obtain information on a refund, contact Winnebago Industries Owner Relations by e-mail at or@winnebagoind.com or write us at Owner Relations Department, P.O. Box 152, Forest City, Iowa 50436, or by telephone at 641/585-6939 or 800/537-1885.

IF YOU HAVE CHANGED ADDRESS OR SOLD THE VEHICLE

If you have changed address or sold or traded your vehicle, please let us know by contacting Winnebago Owner Relations by e-mail at or@winnebagoind.com or in writing at Owner Relations Department, P.O. Box 152, Forest City, Iowa 50436 or by telephone at 641/585-6939 or 800/537-1885.

RP129/5

Page Two

Presentation of this letter to the service center will assist in making the necessary correction to your vehicle in the shortest possible time.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products. This letter does not constitute an acknowledgment of legal liability.

Winnebago Industries, Inc.
Forest City, Iowa 50436

RP129/6

Enclosure