

# Aftermarket Sunroof Safety Recall

## Affected Hollandia 600/700 Model Sunroofs

This recall affects Hollandia 600/700 sunroofs manufactured between January 2002 and May 2009 with serial numbers 6000000 through 6396298. A Hollandia 600/700 sunroof has one pane of glass and will look like the following pictures.



While the car is parked and turned off, if you can carefully place your head up into the opening of your sunroof while looking forward in the vehicle you can locate the serial number label. The label is black and white and should be located either in the center or the driver's side of the vehicle. Next look at the white part of the label for a bold large black number. If your serial number falls between 6000000 and 6396298 your sunroof is covered under this recall.




## Affected Hollandia TVS 900 Model Sunroofs

This recall affects all Hollandia TVS 900 Sunroofs that have reached production prior to May 2010. You can identify a Hollandia TVS 900 sunroof because it has a distinctive two-pane glass roof that looks like the following pictures.



There is a black plastic bar crossing the glass side to side. On this bar is an embossed Webasto logo.



If your sunroof does not have this cross bar or does not have this logo your sunroof is not a Hollandia TVS 900 sunroof.

**If you need help identifying your sunroof or you are ready to get it repaired free of charge, please call [1-888-749-8632](tel:1-888-749-8632) to find out how to get your sunroof serviced or visit [www.sunroofcheck.com](http://www.sunroofcheck.com) for more information.**

**Pursuant to 49 CFR 573, Webasto Product North America, Inc. ("WPNA"), has given notice to the National Highway Traffic Safety Administration ("NHTSA") of its intent to conduct a voluntary safety recall.**

Our records indicate that this company has installed the Hollandia 700/600 and/or Hollandia TVS 900 series aftermarket sunroofs or glass panel service parts that are the subject of this action. It is a violation of federal law to sell any glass panel service parts covered by this recall campaign. WPNA informed NHTSA that a defect that relates to motor vehicle safety might exist in vehicles equipped with certain Hollandia 700/600 and Hollandia TVS 900 series aftermarket sunroofs. Although rare, conditions existing with the adhesive bond between the glass and metal frame in certain Hollandia 700/600 and Hollandia TVS 900 series aftermarket (non-factory installed) sunroofs can increase the risk that the sunroof glass may completely debond from its frame. Completely debonded sunroof glass can detach from the vehicle while driving.

*We regret any inconvenience this action may cause you. The safety and quality of our products are of the utmost importance.*

*Thank you for your attention and cooperation in this matter.*