

Vehicle Safety Recall Quarterly Report Information

Report Date: July 10th 2013

Calendar Quarter (circle one): January 1 – March 31
(April 1 – June 30)
July 1 – September 30
October 1 – December 31

Manufacturer (name, address, phone): Aston Martin Lagonda Limited

Banbury Road, Gaydon, Warwickshire, CV35 ODB, England, UK

Telephone: + 44 (0)1926 644740 Fax: + 44 (0) 1926 644733 e mail: chris.baker@astonmartin.com

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Chris E Baker – General Manager Global After Sales Operations

Contact details as above.

Scott Morgan – Fixed Operations Manager – Aston Martin Lagonda – The Americas
9920 Irvine Center Drive, Irvine CA 92618 USA

Tel: 949-379-3104 – e mail: scott.morgan@astonmartin.com

Subject vehicles (make, model, model year, and any other information necessary for identifying the vehicles):

Aston Martin V12 Vantage – 2010 through 2012 Model Year

1. NHTSA Safety Recall Campaign Number: 12V - 480

Manufacturer's assigned campaign number (where applicable): RA-19-0015

2. (a) The date notification to purchasers began: October 12th 2012

(b) The date notification of purchasers was completed: Regular Dealer follow-up until closure _____

(c) The date notification to dealers and distributors began: October 12th 2012

(d) The date notification of dealers and distributors was completed: October 12th 2012

3. The total number of vehicles involved: 154

NOTE: The number figures given in responses to numbers 5 and 6 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 77 _____

(b) Total number inspected, but determined NOT to require the remedy: 0 _____

5. Numbers of vehicles determined to be unreachable for inspection due to:

Export: _____

Theft: _____

Scrapping: _____

Failure to receive a notification of the recall: _____

Other reasons (specify below): _____

Total number of vehicles unreachable for inspection: _____