

**RECEIVED**

By Recall Management Division at 1:21 pm, Aug 27, 2013

13V-384  
(3 pages)

Safety Defect and Noncompliance Report Guide for Vehicles

PART 573 Defect and Noncompliance Report

Date: 8-12-2013

This report serves as [insert reporting manufacturer's name]'s notification to the U.S. Department of Transportation, National Highway Traffic Safety Administration that a [insert as applicable: "defect related to motor vehicle safety" or "noncompliance with Federal Motor Vehicle Safety Standards"] exists in certain [identify the vehicles at issue]. [Manufacturer] decided that this [insert "defect" or "noncompliance," as applicable] existed in these vehicles on [insert date].

I. Manufacturer, Designated Agent, and Other Chain of Distribution Information

Manufacturer's corporate name: SUNSET PARK RV INC.

Vehicle brand or trademark name owner(s) (where applicable): EZ TRAVELER 21LE

Designated Agent (imported vehicles):

SUNSET PARK RV INC.  
1055N 625W  
SHIPSHAWANA, IN  
Att: Roger West 574-596-7505

If this notification concerns a defective or noncompliant component that the above identified manufacturer did not manufacture, identify that component and provide the name, address, and phone number of the manufacturer of the component (if this manufacturer is unknown, provide this information as to the supplier of the component):

Dometic Corp. Att: David Schutz  
9100 Shelbyville Rd Ste 120  
Louisville, Ky 40222  
502-329-4915

N/A  
Total number of these vehicles:


Make: N/A  
Model: N/A  
Model Year(s):  
Inclusive dates of manufacture (month and year):  
Body Style/Type (for non-passenger cars):  
Other information necessary to describe these vehicles (e.g., VIN range, GVWR or class for trucks, displacement for motorcycles, and number of passengers for buses):  
Total number of these vehicles:

Provide the following information as to all the groups of vehicles:

Grand total number of vehicles: 1

The percentage of the recall population you estimate actually contain the defect or noncompliance: ONLY 1 TRAILER

The End User:



Already has Repair schedule!

Describe the safety consequence(s) of the defect or noncompliance condition.

The Awning Motor will open by itself if under power.

Identify any warning(s) that may precede the defect or noncompliance condition.

Domestic Corp. which built the Awning has a Repair & Replacement Kit and will send it to the end user & pay for the repairs.

For defects, provide a dated, chronological summary of all the principle events that were the basis for the determination that the defect is related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information such as numbers of crashes, injuries and fatalities.

SUNSHINE PARK has no warranty claims or problem as a result of the bad Motor Assemblies.

For noncompliances, identify the test results and other information considered in determining the existence of the noncompliance, and provide the date of each test and observation indicative of that noncompliance. 2013

On April 9th Domestic ran torque tests to determine the sequence point in the assembly instructions found & that during assembly of a anti rotating Cotter Pin was pull out before the assembly was finished that the torque from the motor would rotate to hard & shear off the screws holding the Motor in place.

Identify and describe how the recall population was determined (e.g., on what basis the recalled models were selected and how the inclusive dates of manufacture were determined):

Serial # Range 306 TO 314  
Date Mfg. 02/13/2013 TO 04/09/2013

Describe how the recall population is different from any similar vehicles not subject to this notification:

Domestic Corp. Didnt have any reports of problem with Awning Motor Pre February 13, 2013 or After Post April 9, 2013

### III. Description of the Defect or Noncompliance and Chronology of Events

Describe the defect or noncompliance, including a summary and detailed description of the nature and physical location (if appropriate) of the defect or noncompliance. Graphic aids should be provided where necessary.

Failed Motor Assemblies screws sheared off because of excessive torque from the Motor located in the end of the Awning tub.

Describe the cause(s) of the defect or noncompliance condition.

Torque from the Motor assembly shearing of the screws

IV. The Remedy Program and Its Schedule

Describe the program for remedying the defect or noncompliance, including the plan for reimbursing those owners and purchasers who may have incurred costs to remedy the defect or noncompliance before receiving the manufacturer's notification concerning that defect or noncompliance. Also include, where applicable, details with dates concerning any production remedy that was conducted or will be conducted.

*Sunset Park RV & Domestic Corp is contact the Dealer Derby City RV which in turn will contact the END USER.*

Provide the estimated date(s) on which owner and purchaser notifications will be issued and the estimated date(s) for completion of those notifications.

*As soon as we receive a case number for notification will go out by Sept 1st 2015*

Provide the estimated date(s) on which dealer and distributor notifications will be issued and the estimated date(s) for completion of those notifications.

*By Sept 1st 2015*

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

*Domestic Corp. will send out a Repair kit to bring their product up to code.*

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

*SUNSET PARK RV : Roger West RWest220@MSN.COM  
1055N 625W  
SHIPSHEWANA, IN 46565  
Cell: 574-596-7505 Fx 574-596-7505*

Manufacturer's assigned campaign number (where applicable):

II. Identification of the Recall Population and Its Size

Complete the tables below for each group of vehicles subject to this notification. Additional tables may be necessary where there are more than three groups subject to a notification.

Make:	<i>SUNSET PARK RV</i>
Model:	<i>EZ TRAVELER (21LE)</i>
Model Year(s):	<i>2014</i>
Inclusive dates of manufacture (month and year):	<i>2/19/2013</i>
Body Style/Type (for non-passenger cars):	<i>TRAVEL TRAILER</i>
Other information necessary to describe these vehicles (e.g., VIN range, GVWR or class for trucks, displacement for motorcycles, and number of passengers for buses):	<i>GVWR 3,140 lb - 9100 Power Awning Model # 306 VIN # 4S9BE2126 ES [REDACTED] To 314</i>
Total number of these vehicles:	<i>1</i>

Make:	
Model:	<i>N/A</i>
Model Year(s):	
Inclusive dates of manufacture (month and year):	
Body Style/Type (for non-passenger cars):	
Other information necessary to describe these vehicles (e.g., VIN range, GVWR or class for trucks, displacement for motorcycles, and number of passengers for buses):	