

Equipment Safety Recall Quarterly Report Information

Report Date: September 19, 2013

Calendar Quarter (circle one): ~~January 1 – March 31~~

April 1 – June 30

~~July 1 – September 30~~

~~October 1 – December 31~~

Manufacturer (name, address, phone): KONI North America, LLC

1961-A International Way, Hebron, KY 41048

(859) 586-4100

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Sarah Wilson, Esq., Counsel for KONI by, Covington & Burling LLP, 1201 Pennsylvania Ave.,

NW, Washington, DC 20004, swilson@cov.com, (202) 662-5397, FAX: (202) 778-5397

Gordon Benson, 1961-A International Way, Hebron, KY 41048, gordon.benson@itt.com,

(859) 499-0343, FAX: (859) 334-3340; (800) 209-3350

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Type of Equipment: Shock Absorbers

Part/Model Numbers: 8245-1146L, 8245-1146R, 8245-1201L, 8245-1201E, 8245-1203L, 8245-1203R

Inclusive Dates of Manufacture: January 2008 through April 2013

1. NHTSA Safety Recall Campaign Number: 13E-023

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: May 16, 2013

(b) The date notification of purchasers was completed: May 16, 2013

(c) The date notification to dealers and distributors began: May 16, 2013

(d) The date notification of dealers and distributors was completed: May 16, 2013

3. The total number of items of equipment involved: 39

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 8

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: 8

Theft: 0

Scrapping: 2

Failure to receive a notification of the recall: 19

Other reasons (specify below): 2

~~Customer is in contact with us. Replacements sent to customer. Waiting to received old units back.~~

Total number of items of equipment unreachable for inspection: 31

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 14 (not included in 39 total)