



Product Recall Orbit Baby Car Seat Base G2



Included in recall:

- Product: **Orbit Baby Car Seat Base G2** (Model No. ORB822000)
- Date Manufactured: Between **March 20, 2013 and July 20, 2013**
- Batch Numbers: **A0840, A0860 and A0880**

IMPORTANT NOTE: This recall only affects the Orbit Baby Car Seat Base G2. The Infant Car Seat G2 (Model No. ORB833000) is NOT included in this recall.



Included in recall



StrongArm knob



Manufacturing label:
Model Number, Date Manufactured, Batch Number



Orbit Baby has received reports that the StrongArm Knobs on some of the affected Car Seat Base G2 units may detach or may just spin without tightening the base. The StrongArm mechanism tightens the car seat base into the vehicle. In either of these cases, the Car Seat Base G2 cannot be installed securely because you must tighten the base into the vehicle by using the StrongArm mechanism.

This issue does NOT affect the Orbit Baby Infant Car Seat G2 (Model No. ORB833000), which can be installed with or without the Car Seat Base G2. The Infant Car Seat G2

can continue to be used without the base until the repair kit has been installed.

Look for the manufacturing label on the back of the base upright. This label displays the model number, date manufactured and batch number.

If you have not yet received your repair kit and have concerns, your Infant Car Seat G2 can continue to be used by installing the Infant Car Seat G2 without the Car Seat Base G2 in accordance with the instruction manual.

Contact Orbit Baby to receive a free repair kit at:
support@orbitbaby.com or 1-877-ORB-BABY (1-877-672-2229), or visit

www.orbitbaby.com/safety-update



Post until December 2013

In cooperation with the National Highway Traffic Safety Administration. Recall No. 13C-003
Updated October 2013. For US distribution only. ©2013 Orbit Baby, Inc. MA030.1 | OCT2013