

## Vehicle Safety Recall Quarterly Report Information

Report Date: July 16, 2014

Calendar Quarter (circle one): January-March 31

**April 1-June 30**

July 1 – Sept 30

Oct 1- Dec 31

Manufacturer (Name, address, phone): Explorer Van Company, Inc.

PO Box 4527

Warsaw, IN 46581-4527

(574) 267-7666

Name, address, email, and phone and fax numbers for the person to whom inquiries about this report should be directed:

Ronald J. Ehinger

Barrett & McNagny LLP

215 E. Berry Street

Fort Wayne, IN 46802

(260) 423-9551

Fax: (260) 423-8920

Subject vehicles (make, model, model year, and any other information necessary for identifying the vehicles): Chevrolet/Express/2013

GMC/SA Van/ 2013

1. NHTSA Safety Recall Campaign Number: 13V-147  
Manufacturer's assigned campaign number (where applicable): 2013-1
2. (a) The date notification to purchasers began: May 10, 2013  
  
(b) The date notification of purchasers was completed: May 15, 2013  
  
(c) The date notification to dealers and distributors began: May 7, 2013  
  
(d) The date notification to dealers and distributors was completed: May 10, 2013
3. The total number of vehicles involved: 885

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information)

4. (a) Total number inspected and remedied: 0\*

(b) Total number inspected, but determined NOT to require the remedy for 04/01/14 to 06/30/14:

3\*\*

(c) Total number inspected, but determined NOT to require the remedy (cumulative):

223\*\*

5. Number of vehicles determined to be unreachable for inspection due to:

Export: \_\_\_\_\_

Theft: \_\_\_\_\_

Scrapping: \_\_\_\_\_

Failure to receive a notification of the recall: \_\_\_\_\_

Other reasons (specify below) \_\_\_\_\_

---

---

---

Total number of vehicles unreachable for inspection: \_\_\_\_\_

\* None of the vehicles inspected had any damaged wires or cables.

\*\* Dealers were asked to route wires and install ties in accordance with the provided instructions in all cases where the inspections were done.