



IMPORTANT SAFETY RECALL

This notice applies to your vehicle [insert VIN]

June 2014

This notice is sent to you in accordance with the requirements of the National Traffic and *Motor Vehicle Safety Act*.

Micro Bird decided that a defect which relates to motor vehicle safety exists in certain 2011 through 2013 model year Micro Bird Ford G5 school bus manufactured from 2010/09/20 through 2013/06/13 and equipped with the optional Roush CleanTech LLC propane fuel system. Our records show that you own the vehicle(s) with the vehicle identification number shown above (or on the reply sheet).

In severe environments, the aluminum fuel line fitting at the propane tank can experience galvanic corrosion where it contacts the brass supply valve housing on the fuel tank. This could result in a leak of the propane fuel, which could lead to a fire.

To remedy this condition the aluminum fuel supply valve fitting on the Roush CleanTech propane tank will be replaced with a new stainless steel fuel supply fitting. Only Roush CleanTech propane tank identified in annex within the following range of propane tank serial number installed on Micro Bird buses are affected by this recall.

Replacement stainless steel fuel supply valve fittings will be provided to you at no cost.

You may contact your Micro Bird dealer to arrange to have this recall performed. Be sure to have your Micro Bird VIN number when you place your call.

Or, you may contact your nearest Roush CleanTech Authorized Service Center to have this recall performed. If you need help in locating the nearest Roush CleanTech Authorized Service Center you may call Roush CleanTech at 1-800-597-6874 and Roush CleanTech will provide further instructions on how to have your bus repaired. Be sure to have your Micro Bird VIN number available when you place your call.

If you prefer, you may have qualified personnel perform the repairs work on the propane autogas system. You may perform this recall remedy yourself or you may have a repair facility



IMPORTANT SAFETY RECALL

convenient to you that is qualified to work on propane autogas systems perform this recall remedy.

Labor time to replace the propane fuel tank valve fitting is 0.5 (30 minutes) per bus.

Repair performed by a Micro Bird dealer or Roush CleanTech Authorized Service Center will be performed at no charge to you.

If the recall remedy is performed by your qualified personnel or a qualified repair facility, reimbursement for labor may be obtained by completing the enclosed Reply Sheet and returning to Micro Bird by fax 1-819-475-9633 or email.

If you no longer own the subject bus (es), please complete the appropriate section of this sheet and return to Micro Bird by fax 1-819-475-9633 or email.

If the modification directed by this notification were performed on your bus prior to the receipt of this recall notification, complete and sign the reply sheet and attach a copy of the work order/ invoice to Marie-Claude Vigneault at Micro Bird Service and Warranty at Marie-Claude.Vigneault@microbird.com

If you have leased this vehicle to another person or organization, you must forward this letter to the lessee within 10 days.

If you require any further assistance, please call our after-sale service at 1-819-477-2012 extension 264. Please have your vehicle identification number ready for our representative when you call.

Recall 14-057-RSU - NHTSA 14V-337



IMPORTANT SAFETY RECALL

Should Micro Bird fail or be unable to remedy the situation without charge, you may contact:

Associate Administrator, National Highway Traffic Safety Administration

1200 New Jersey Ave S.E., Washington, DC 20590

Phone: (888) 327-4236 (TTY: 1-800-424-9153); or go to

<http://www.safercar.gov>

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition.

Best regards,

Nadia James
Regulations and Standards Technician
Corporation Micro Bird Inc.



IMPORTANT SAFETY RECALL

Recall 14-057-RSU (NHTSA recall #)

DO NOT COMPLETE THIS SECTION UNLESS: Your company had a name change, has moved or no longer own this vehicle.

Vehicle serial number:

- _____
- This vehicle was stolen.
 - This vehicle was destroyed.
 - The name of the company has changed or we have moved (indicate new name/address and phone number):
 - I no longer own the vehicle, it has been sold or traded to:

Name:

Address:

City:

—

State:

Phone:

Zip

code:

Signature: _____ Date:
