

**Toyota Motor Engineering &
Manufacturing North America, Inc.**

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

October 1, 2014

Re: FMVSS 110, Tire Selection and Rims for Passenger Cars
Part 573, Noncompliance Information Report

In connection with the above referenced matter, this supplements Toyota's letter of August 4, 2014.

The affected vehicle VIN range is indicated below:

Identification of Affected Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Toyota/ Tacoma	2008- 2014	TMMBC TMMTX NUMMI	****N	M005100 – M173932 X001026 - X109626 Z469952 - Z749134	August 3, 2007 to July 29, 2014
Toyota/ FJ Cruiser	2008- 2014	TMC	*U11F	K001087-K070001 0019078-0107218	July 11, 2007 to July 21, 2014
			*U4BF	K008629 – K206735	