

Federal Recall Information

13KWM

Supplier

Grote Industries, LLC

Description

Recall 13KWM - Grote STT Lamp Campaign

Release Date

1/27/2014

Introduction

Kenworth has decided that certain 2013 Kenworth models (T170, T270, T370, T440, T470, T660, T680, T700, T800, T880, W900, and C500) manufactured from July 1, 2013, through September 17, 2013 are equipped with noncompliant STT lamps, where the lamp does not fit securely into the retention ring and therefore could allow the lamp to fall out.

Situation

5,788 chassis were manufactured with the non conforming Grote lamp assemblies, with a date code stamped.

Resolution

A permanent design solution was implemented into production. Chassis listed on the attached chassis list require new replacement Grote STT lamp assemblies. See Parts and section below. Replace lamp assemblies following the procedure attached. Destroy take-off parts. See Attachment section below.

Purge parts inventory of all STT lamps with date codes between 130624 (June 24, 2013) and 130905 (Sept. 5, 2013). Dealers showing current inventory of the impacted parts were notified January 10,

2014 with RGA and return information to have product returned to Grote. Grote will send replacement parts upon receipt of the impacted parts.



It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

The DWC system will indicate chassis involved in this recall with the designator of "**13KWM**" in the campaign field.

See Parts section below for correct replacement part number and Quick Claims.

Claim Details:

For Field...	Enter...
Failure Location	034-002-022
Failure Type	705 – Safety Recall
Claim Type	C
Campaign Number	13KWM
Labor	SRT 034-XXX @ 0.2 hours Remove and Replace
CCC Notes	Recall Grote STT Lamp

Parts

Service Kit: 01-5390-73GR0 (includes 2 lamp assemblies)

QUICK CLAIMS

13KWMA – Grote STT Lamp R&R.

13KWMB – Lamp has been removed.

Labor

13KWMA: 0.2 hours/chassis

13KWMB: 0.1 hours/chassis

Procedure

See replacement procedure below.

Attachments

 [Replacement Procedure](#) (5/23/2014)

 [Chassis\Dealer List](#)

 [U.S. Customer Letter](#) |  [Canadian Letter](#)

Authored by: BB