



IMPORTANT SAFETY RECALL

NHTSA Safety Recall 15V-581

THIS NOTICE APPLIES TO YOUR VEHICLE.

**RE: BODY SERIAL
CHASSIS SERIAL**

Dear Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Our records indicate that you have purchased a vehicle with the serial number which appears above.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2015 and 2016 model year Winnebago Sightseer[®] and Itasca Sunova[®] (Model D35G) motorhomes.

These motorhomes were manufactured March 19, 2015 through July 15, 2015. These vehicles may not have enough clearance for the wire loom behind the panel board when left rear slideout room is retracted. Contact with the wire loom is possible depending on how the wire loom was routed. If this should occur, the conductors within the wire loom may be damaged or pinched. Damaged or pinched wires have the potential to heat up and create a fire.

WHAT WE WILL DO

Winnebago Industries, Inc. dealers will route the wire loom and install clamps at no charge to you. If there is evidence of damage to any conductors, they will be replaced at no charge to you.

WHAT YOU SHOULD DO

Please contact your Winnebago Industries, Inc. dealer immediately to arrange for an appointment. The labor time necessary to perform this correction will be approximately one hour. Please allow time for the dealer to process your vehicle.

Winnebago Industries, Inc. dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to the dealer on the agreed date and he does not service this condition on that date or within five days, we recommend you contact Winnebago Industries, Inc., Attn.: Owner Relations Representative (641-585-6939). If you are still unable to obtain such service without charge to you and within a reasonable time, you may contact The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, DC 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

IF YOU HAVE PREVIOUSLY PAID FOR THIS REPAIR

If you have paid to remedy this issue, you may be eligible for a refund. To obtain information on a refund, contact Winnebago Owner Relations by email at or@winnebagoind.com or write us at Owner Relations Department, P.O. Box 152, Forest City, Iowa 50436 or by telephone at (641) 585-6939 or (800) 537-1885.

TO103 US/3

IF YOU HAVE CHANGED ADDRESS OR SOLD THE VEHICLE

If you have changed address or sold or traded your vehicle, please let us know by contacting Winnebago Owner Relations by email at or@winnebagoind.com or in writing at Owner Relations Department, P.O. Box 152, Forest City, Iowa 50436 or by telephone at (641) 585-6939 or (800) 537-1885.

Presentation of this letter to the service center will assist in making the necessary correction to your vehicle in the shortest possible time.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products. This letter does not constitute an acknowledgment of legal liability.

Winnebago Industries, Inc.
Forest City, Iowa 50436

TO103 US/4

Enclosure