

Part 573 Safety Recall Report**16V-026****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** JAN 19, 2016**NHTSA Recall No. :** 16V-026**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152

605 W. Crystal Lake Rd. Forest City IA 50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 359

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2015-2016 Winnebago Travato, Trend

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : ProMaster ignition switch

Production Dates : FEB 27, 2015 - JAN 06, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2016 Itasca Viva!

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : ProMaster Ignition switch recall

Production Dates : FEB 27, 2015 - JAN 06, 2016

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some vehicles may experience an intermittent loss of electrical contact inside the ignition switch

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loss of motive power and/or a partial or complete drop-out of the following

safety systems: Airbags, Anti-Lock Brakes, Electronic Stability Control, and/or instrument panel cluster.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

1-14-16 Customer contacted us asking if their motorhome was affected by the ProMaster recall. We contact Promaster.

1-15-16 We start working with ProMaster to identify our units that are in their recall.

1-19-16 Completed our research and input our 573 information into the NHTSA recall portal.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : To be done by ProMaster

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported